


## Clamping System

A clamping screw pushes the shank of the tool through a narrowed opening forcing elastic deformation of the steel holder and face contact.

As the steel contracts around the tool, contact is made around slightly more than a full 180°. The result is rigidity comparable to a solid part.

## Extention Options



Face Contact Over 180° Peripheral Surface Contact

## System Overview

